



## Vergleich der Sanierungs-Varianten


Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach




Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach




Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach




Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach




Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach




Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach



Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach



Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach



Ist-Zustand - Ist-Zustand  
 Var.1 - Fenster&HET  
 Var.2 - WDVS  
 Var.3 - Dach

